

*California Department of Transportation
Division of Maintenance*

Structure Maintenance and Investigations

B_{RIDGE}

I_{NSPECTION}

R_{ECORDS}

I_{NFORMATION}

S_{YSTEM}

The requested documents have been generated by BIRIS.

These documents are the property of the California Department of Transportation and should be handled in accordance with Deputy Directive 55 and the State Administrative Manual.

Records for “Confidential” bridges may only be released outside the Department of Transportation upon execution of a confidentiality agreement.



DEPARTMENT OF TRANSPORTATION
Structure Maintenance & Investigations

Bridge Number : 27 0023
Facility Carried: STATE ROUTE 1
Location : 04-MRN-001-28.51
City :
Inspection Date : 05/07/2014

Bridge Inspection Report

Inspection Type
Routine FC Underwater Special Other
☒

STRUCTURE NAME: LAGUNITAS CREEK

CONSTRUCTION INFORMATION

Year Built : 1929 Skew (degrees): 0
Year Widened: N/A No. of Joints : 2
Length (m) : 46.3 No. of Hinges : 0

Structure Description: RC deck on riveted steel floor beams on riveted steel pony truss main span and RC T-beam (5) end spans on RC piers and RC abutments. The piers are founded on piles and the abutments are founded on spread footings.

Span Configuration : 1 @ 7.32 m, 1 @ 30.48 m, 1 @ 7.32 m

SAFE LOAD CAPACITY AND RATINGS

Design Live Load: MS-13.5 OR HS-15
Inventory Rating: RF=0.67 =>21.7 metric tons Calculation Method: ALLOWABLE STRESS
Operating Rating: RF=1.11 =>36.0 metric tons Calculation Method: ALLOWABLE STRESS
Permit Rating : XXXXX
Posting Load : Type 3: Legal Type 3S2: Legal Type 3-3: Legal

DESCRIPTION ON STRUCTURE

Deck X-Section: 1.2 m sw, 0.21 m cu, 7.32 m, 0.21 m cu
Total Width: 8.8 m Net Width: 7.3 m No. of Lanes: 2 Speed: 35 mph
Min. Vertical Clearance: Unimpaired
Rail Code: 0000

Rail Type	Location	Length (ft)	Rail Modifications
Misc.	Right/Left	306	
Steel			

DESCRIPTION UNDER STRUCTURE

Channel Description: Sandy silt.

INSPECTION COMMENTARY

SCOPE AND ACCESS

The river was flowing under Span 2 only at the time of the inspection. Both abutments and Pier 2 were out of water. The substructure could not be inspected under Pier 3 due to the substantial depth of the water in Span 2 side. All other substructure elements were inspected. The inspection for the superstructure was limited to the deck, rails and left steel truss from the left sidewalk.

A fracture critical inspection dated 10/24/2013 was conducted in accordance with the Fracture Critical Member Inspection Plan. This bridge is fracture critical because it is a truss with low redundancy. It also has riveted connection and Category D detail on tension chord.

DECK AND ROADWAY

There are new AC approach pavements to both abutments.

The original steel sliding expansion joints at the abutments have been cut and removed to modify them as open expansion joints. However, at the time of this inspection and

INSPECTION COMMENTARY

temperature of 70 degree Fahrenheit, there was no gap between the open expansion joints on either abutment (see 5/24/2012 archived photos).

The RC deck of the approach spans in Spans 1 and 3 have 1/16 inch wide longitudinal and diagonal cracks which were treated with methacrylate in 2014 under Contract 04-04H820.

The RC deck of the steel truss span in Span 2 has 1/32 inches wide longitudinal, transverse, and pattern cracks which were treated with methacrylate in 2011 under Contract 04-0E9801.

The steel bridge rails facing traffic have moderate rust and are spotted with fungus growth. Some of the riveted connections on the rails have up to 1/3 inches of pack rust under them.

There is a 2 feet X 1 feet opening on the timber flooring at the left sidewalk where it meets left steel truss near Pier 3 (see 5/12/2012 archived photos). A work recommendation is proposed to close the hole.

SUPERSTRUCTURE

Some of the steel gusset plates connecting the bridge rails to the vertical truss members have up to 1/4 inches of pack rust at each corner of the plate.

There is up to 1/4 inches of pack rust between the corners of the steel gusset plates and the bottom chord of the steel truss (see 10/27/2010 archived photos).

The steel gusset plate connections at L4 left and right have pack rust up to 1.5 inches of expansion visible between plates. The pack rust has been painted over, however, the paint is beginning to fail leaving a 1/4 inches open gap (see 5/24/2012 archived photos).

The top chord of both steel trusses has a few areas of spot rust and up to 1/8 inch of pack rust found mainly at the edges of the gusset plate connections.

There are randomly spaced 1/32 inch wide vertical cracks in the RC beams in the approach spans.

There is a 6 inches x 6 inches x 4 inches triangular spall in the bottom corner of the RC slab, where the slab meets the steel floor beam, at the eighth panel point on the right side of the structure.

There are 1/32 inch wide pattern cracks in the RC soffit throughout the steel truss portion of the structure. There is a 36 inches longitudinal soffit crack about between the first and second floor beam that is beginning to spall. There is also a 48 inches x 16 inches spall with one exposed longitudinal rebar in the left side of the RC soffit in Bay 5.

There is up to 1/2 inch of pack rust along the top flanges of the steel floor beams where they meet the RC slab.

The steel lateral braces in Bays 4 and 6 are bent. This deformation was most likely caused by the forces of flood waters and the lodging of drift between the floor beams and the bracing.

There is one corroded rivet head at the left floor beam connection in Bay 6.

SUBSTRUCTURE

There is a 1/64 inch wide and 3 feet long diagonal crack in Bent 3 (right) under the

INSPECTION COMMENTARY

steel truss supporting point (see 5/24/2012 archived photos).

The Abutment 4 wall and the soffit of Span 3 are covered with graffiti, however, it is not in public view.

The timber fenders at Piers 2 and 3 have decayed and are deteriorating (see attached photo 1).

The bolts on the steel fixed bearings are rusty and bent toward Abutment 1 at an angle of about 30 degrees.

The steel rocker bearings are tilted toward Abutment 4 at an angle of approximately 30 degrees. They appear to be in good working condition (see 5/11/2010 archived photos).

The paint on the steel truss members, floor beams, lateral braces and bearings has some faded and chalky areas, as well as occasional surface and edge rust. Pack rust is present at some of the connections.

SAFE LOAD CAPACITY

A Load Rating Summary Sheet dated 6/30/2010 is on file for this structure. The load rating for this structure is being reviewed by SMI Ratings Branch. An updated Load Rating Summary will be archived when this review is complete. The current rating is based on Working Stress method dated 8/23/1978.

STEEL INVESTIGATIONS

This structure qualifies for an in-depth Steel investigation because it possesses the following fracture critical or fatigue prone details :

Floor Beams: FC Members,

Truss: FC Members

Fracture Critical: Yes

Inspection Freq.: 24

Next Inspection: 10/24/2015

<u>ELEMENT INSPECTION RATINGS</u>									
Elem No.	Element Description	Env	Total Qty	Units	Qty in each Condition State				
					St. 1	St. 2	St. 3	St. 4	St. 5
12	Concrete Deck - Bare	2	408	sq.m	408	0	0	0	0
121	Painted Steel Bottom Chord Thru Truss	2	30	m.	0	20	10	0	0
126	Painted Steel Thru Truss (excl. bottom chord)	2	61	m.	36	15	10	0	0
152	Painted Steel Floor Beam	2	85	m.	0	0	85	0	0
227	Reinforced Conc Submerged Pile	2	1	ea.	1	0	0	0	0
304	Open Expansion Joint	2	18	m.	0	18	0	0	0
311	Moveable Bearing (roller, sliding, etc.)	2	2	ea.	2	0	0	0	0
313	Fixed Bearing	2	2	ea.	1	1	0	0	0
330	Metal Bridge Railing - coated or uncoated	2	93	m.	0	83	10	0	0
357	Pack Rust	2	1	ea.	0	1	0	0	0
358	Deck Cracking	2	1	ea.	1	0	0	0	0
359	Soffit of Concrete Deck or Slab	2	1	ea.	0	1	0	0	0

WORK RECOMMENDATIONS

Printed on: Thursday 07/24/2014 01:41 PM

27 0023/AAAN/29048

WORK RECOMMENDATIONS

RecDate: 05/07/2014	EstCost: \$2,600	Close the hole on the timber flooring at the left sidewalk where it meets left steel truss near Pier 3.
Action : Deck-Repair Potholes	StrTarget: 2 YEARS	
Work By: BRIDGE CREW	DistTarget:	
Status : PROPOSED	EA:	
RecDate: 05/21/2012	EstCost: \$1,500	Methacrylate both approach spans to fill the cracks and extend the service life of the deck.
Action : Deck-Methacrylate	StrTarget: 2 YEARS	
Work By: MAINT. CONTRACT	DistTarget:	
Status : PROGRAMMED	EA: 4H820	
RecDate: 05/11/2010	EstCost: \$380,800	Paint all steel elements of the bridge. Steel members have faded and there are edge rust and pack rust present at the connections.
Action : Paint-Full Prep	StrTarget: 2 YEARS	
Work By: MAINT. CONTRACT	DistTarget:	
Status : INITIATED	EA: 0G642	
RecDate: 03/28/2007	EstCost: \$205,000	Steel truss members may require strengthening. Priority 4. Final Score 1.75.
Action : Seismic-Retrofit	StrTarget: 2 YEARS	
Work By: STRAIN	DistTarget:	
Status : INITIATED	EA: 0G642	
RecDate: 02/10/1984	EstCost: \$191,880	F1-06 / F2-0 / F3-5 / Rail Type-SR
Action : Railing-Upgrade	StrTarget: 2 YEARS	
Work By: STRAIN	DistTarget:	
Status : INITIATED	EA: 0G642	

Team Leader : Beau Trinh

Report Author : Beau Trinh

Inspected By : B.Trinh/T.Le

Beau Trinh 7/24/14
 Beau Trinh (Registered Civil Engineer) (Date)



STRUCTURE INVENTORY AND APPRAISAL REPORT

***** IDENTIFICATION *****

(1) STATE NAME- CALIFORNIA 069
 (8) STRUCTURE NUMBER 27 0023
 (5) INVENTORY ROUTE (ON/UNDER) - ON 131000010
 (2) HIGHWAY AGENCY DISTRICT 04
 (3) COUNTY CODE 041 (4) PLACE CODE 00000
 (6) FEATURE INTERSECTED- LAGUNITAS CREEK
 (7) FACILITY CARRIED- STATE ROUTE 1
 (9) LOCATION- 04-MRN-001-28.51
 (11) MILEPOINT/KILOMETERPOINT 28.51
 (12) BASE HIGHWAY NETWORK- PART OF NET 1
 (13) LRS INVENTORY ROUTE & SUBROUTE 000000000101
 (16) LATITUDE 38 DEG 03 MIN 52.41 SEC
 (17) LONGITUDE 122 DEG 48 MIN 18.46 SEC
 (98) BORDER BRIDGE STATE CODE % SHARE %
 (99) BORDER BRIDGE STRUCTURE NUMBER

***** STRUCTURE TYPE AND MATERIAL *****

(43) STRUCTURE TYPE MAIN: MATERIAL- STEEL
 TYPE- TRUSS - THRU CODE 310
 (44) STRUCTURE TYPE APPR: MATERIAL- CONCRETE
 TYPE- TEE BEAM CODE 104
 (45) NUMBER OF SPANS IN MAIN UNIT 1
 (46) NUMBER OF APPROACH SPANS 2
 (107) DECK STRUCTURE TYPE- CIP CONCRETE CODE 1
 (108) WEARING SURFACE / PROTECTIVE SYSTEM:
 A) TYPE OF WEARING SURFACE- NONE CODE 0
 B) TYPE OF MEMBRANE- NONE CODE 0
 C) TYPE OF DECK PROTECTION- NONE CODE 0

***** AGE AND SERVICE *****

(27) YEAR BUILT 1929
 (106) YEAR RECONSTRUCTED 0000
 (42) TYPE OF SERVICE: ON- HIGHWAY-PEDESTRIAN 5
 UNDER- WATERWAY 5
 (28) LANES: ON STRUCTURE 02 UNDER STRUCTURE 00
 (29) AVERAGE DAILY TRAFFIC 3000
 (30) YEAR OF ADT 2009 (109) TRUCK ADT 4 %
 (19) BYPASS, DETOUR LENGTH 10 KM

***** GEOMETRIC DATA *****

(48) LENGTH OF MAXIMUM SPAN 30.5 M
 (49) STRUCTURE LENGTH 46.3 M
 (50) CURB OR SIDEWALK: LEFT 1.2 M RIGHT 0.2 M
 (51) BRIDGE ROADWAY WIDTH CURB TO CURB 7.3 M
 (52) DECK WIDTH OUT TO OUT 8.8 M
 (32) APPROACH ROADWAY WIDTH (W/SHOULDERS) 6.7 M
 (33) BRIDGE MEDIAN- NO MEDIAN 0
 (34) SKEW 0 DEG (35) STRUCTURE FLARED NO
 (10) INVENTORY ROUTE MIN VERT CLEAR 99.99 M
 (47) INVENTORY ROUTE TOTAL HORIZ CLEAR 7.3 M
 (53) MIN VERT CLEAR OVER BRIDGE RDWY 99.99 M
 (54) MIN VERT UNDERCLEAR REF- NOT H/RR 0.00 M
 (55) MIN LAT UNDERCLEAR RT REF- NOT H/RR 0.0 M
 (56) MIN LAT UNDERCLEAR LT 0.0 M

***** NAVIGATION DATA *****

(38) NAVIGATION CONTROL- NO CONTROL CODE 0
 (111) PIER PROTECTION- CODE
 (39) NAVIGATION VERTICAL CLEARANCE 0.0 M
 (116) VERT-LIFT BRIDGE NAV MIN VERT CLEAR M
 (40) NAVIGATION HORIZONTAL CLEARANCE 0.0 M

***** SUFFICIENCY RATING *****

SUFFICIENCY RATING = 38.3
 STATUS STRUCTURALLY DEFICIENT
 HEALTH INDEX 71.1
 PAINT CONDITION INDEX = 65.9

***** CLASSIFICATION ***** CODE

(112) NBIS BRIDGE LENGTH- YES Y
 (104) HIGHWAY SYSTEM- NOT ON NHS 0
 (26) FUNCTIONAL CLASS- MINOR ARTERIAL RURAL 06
 (100) DEFENSE HIGHWAY- NOT STRAHNET 0
 (101) PARALLEL STRUCTURE- NONE EXISTS N
 (102) DIRECTION OF TRAFFIC- 2 WAY 2
 (103) TEMPORARY STRUCTURE-
 (105) FED. LANDS HWY- NOT APPLICABLE 0
 (110) DESIGNATED NATIONAL NETWORK - NOT ON NET 0
 (20) TOLL- ON FREE ROAD 3
 (21) MAINTAIN- STATE HIGHWAY AGENCY 01
 (22) OWNER- STATE HIGHWAY AGENCY 01
 (37) HISTORICAL SIGNIFICANCE- NOT ELIGIBLE 5

***** CONDITION ***** CODE

(58) DECK 6
 (59) SUPERSTRUCTURE 4
 (60) SUBSTRUCTURE 7
 (61) CHANNEL & CHANNEL PROTECTION 7
 (62) CULVERTS N

***** LOAD RATING AND POSTING ***** CODE

(31) DESIGN LOAD- MS-13.5 OR HS-15 3
 (63) OPERATING RATING METHOD- ALLOWABLE STRESS 2
 (64) OPERATING RATING- 36.0
 (65) INVENTORY RATING METHOD- ALLOWABLE STRESS 2
 (66) INVENTORY RATING- 21.7
 (70) BRIDGE POSTING- EQUAL TO OR ABOVE LEGAL LOADS 5
 (41) STRUCTURE OPEN, POSTED OR CLOSED- A
 DESCRIPTION- OPEN, NO RESTRICTION

***** APPRAISAL ***** CODE

(67) STRUCTURAL EVALUATION 4
 (68) DECK GEOMETRY 2
 (69) UNDERCLEARANCES, VERTICAL & HORIZONTAL N
 (71) WATER ADEQUACY 8
 (72) APPROACH ROADWAY ALIGNMENT 8
 (36) TRAFFIC SAFETY FEATURES 0000
 (113) SCOUR CRITICAL BRIDGES U

***** PROPOSED IMPROVEMENTS *****

(75) TYPE OF WORK- REPLACE FOR DEFICIENCY CODE 31
 (76) LENGTH OF STRUCTURE IMPROVEMENT 46.3 M
 (94) BRIDGE IMPROVEMENT COST \$943,000
 (95) ROADWAY IMPROVEMENT COST \$188,600
 (96) TOTAL PROJECT COST \$1,584,240
 (97) YEAR OF IMPROVEMENT COST ESTIMATE 2010
 (114) FUTURE ADT 4606
 (115) YEAR OF FUTURE ADT 2036

***** INSPECTIONS *****

(90) INSPECTION DATE 05/14 (91) FREQUENCY 24 MO
 (92) CRITICAL FEATURE INSPECTION: (93) CFI DATE
 A) FRACTURE CRIT DETAIL- YES 24 MO A) 10/13
 B) UNDERWATER INSP- NO MO B)
 C) OTHER SPECIAL INSP- NO MO C)